

Infraserv GmbH • Gleiwitzerstraße 8 • 85386 Eching

# CERTIFICATION

<b>Helium – leak - check</b>	<b>SNIFFER - TEST</b>
<b>Date:</b>	<b>14 – 11 - 2008</b>
<b>Location:</b>	<b>high - vacuum area</b>
<b>Object:</b>	<b>Dichtungseinsatz A</b>
<b>Based on:</b>	<b>DIN EN 1779 Anhang B3</b>
<b>Charging pressure:</b>	<b>1000 mbar</b>
<b>First Test:</b>	<b>&lt; 1·10<sup>-7</sup> mbar·l/s</b>
<b>Test after 17 hours:</b>	<b>1,1·10<sup>-4</sup> mbar·l/s</b>

<b>Terms of environmental:</b>	Temperature :	<b>24°C</b>	Humidity. :	<b>34 %</b>
--------------------------------	---------------	-------------	-------------	-------------

<b>Calibration-standard:</b>	<b>Internal testleak</b>			
	Reference N.:	-----		
	Date of calibration:	-----		

<b>Helium-leakdetector:</b>	<b>Adixen</b>			
	Modell :	<b>ASM , 142 G</b>		
	Serien Nr.:	<b>30174</b>		

Infraserv GmbH  
Gleiwitzerstraße 8  
85386 Eching

Geschäftsführer:  
Dipl. Ing.  
Christian Maenecke

Tel: 089 319 01 03  
Fax: 089 31 90 10 50

E-Mail:  
info@infraservgmbh.com  
www.infraservgmbh.com

Postfach Adresse:  
Postfach: 11 44  
85378 Eching

Bankverbindung:  
Sparkasse Freising  
BLZ: 700 510 03  
Kto: 146 782 62

Dresdner Bank  
BLZ: 700 800 00  
Kto: 07841 851 00

Handelsregister München;  
HRB 101844

USt-Id-NR.:  
DE 156015582

**Passed:**  
Hermann Scharl  
Technical Director



**Operator:**  
V. Hoffmann  
Technician


